FMC Corporation

Phosphorus Chemicals Division PO Box 4111 Pocatello, Idaho 83205 (208) 236-8200





February 28, 2001

Ms. Linda Meyer U.S. Environmental Protection Agency, Region 10 1200 Sixth Avenue Seattle, WA 98101

Subject: Astaris Idaho LLC, EPA ID No. IDD 07092 9518

Pond 8S Post-Closure Monitoring and Inspection Summary for 2000

Dear Ms. Meyer:

Enclosed please find Pond 8S Post-Closure Monitoring and Inspection Summary for 2000. This report is being submitted to EPA for information purposes only.

Overall, acceptable conditions were noted throughout the monitoring period for the final cover and monitoring systems. No temperature alarms were triggered at the Temperature Monitoring Points (TMPs), and no pressure alarms were triggered by the pressure monitoring system. No water was pumped from the cap drainage subdrain outlets #1 or #2 during the monitoring period. Therefore, the total cap drainage / infiltration rate was zero for the monitoring period.

Per the Pond 8S Post-Closure Plan, post-closure monitoring will continue at Pond 8S. Please feel free to contact me at (208) 236-8658 should you have questions regarding this information.

Very truly yours,

Rob J. Hartman

FMC Corporation

Enclosure

cc: Wallace Reid, EPA w/ enclosure

Susan Hanson, Shoshone-Bannock Tribes w/ enclosure



POND 8S POST-CLOSURE Monitoring and Inspection Summary for 2000

Astaris Idaho LLC EPA ID No. IDD 07092 9518

February 28, 2001



POND 8S POST-CLOSURE Monitoring and Inspection Summary for 2000

February 28, 2001

A summary of the post-closure monitoring and inspection activities performed at Pond 8S during the first year of post-closure monitoring (October 1999 through December 2000) is provided below. The summary is generally organized in the same order as on Table 10-1 Post-Closure Activity Checklist from the Pond 8S post-closure plan. A copy of Table 10-1 is attached for reference.

Attachment A is a copy of the Temperature and Pressure Monitoring Results, Quarterly Monitoring Equipment Inspection forms, and Quarterly Groundcover Inspection forms presented by quarter for 4th quarter 1999 through 4th quarter 2000. Attachment B is a summary of the quarterly Gas Monitoring Point (GMP) soil gas monitoring results for 4th quarter 1999 through 4th quarter 2000. These attachments are referenced under the relevant sections below.

Groundwater Monitoring

Groundwater monitoring was conducted quarterly per the Pond 8S post-closure plan and RCRA Interim Status Groundwater Monitoring Plan (August 1999) for the facility. The monitoring results are provided under separate cover in the "RCRA Interim Status 2000 Groundwater Monitoring Assessment," that is submitted to EPA on or before March 1, 2001. In summary, monitored constituent concentrations were at or below levels measured during the previous year (1999). As in prior monitoring events, elemental phosphorus was not detected in the Pond 8S groundwater wells 155, 156 and 157 (downgradient wells) during the semi-annual monitoring events (May and November 2000).

Quarterly Inspections

Acceptable conditions were noted throughout the monitoring period. Items that required follow-up are summarized below. Copies of the Quarterly Monitoring Equipment and Groundcover Inspection forms are included in Attachment A.

- Cap and cover: Acceptable conditions were noted throughout the monitoring period.
 Potential rodent activity on the cap will continue to be monitored in spring 2001, and may require trapping and relocation if rodent activity is still noted.
- Settlement monuments: Acceptable conditions were noted throughout the monitoring period. Erosion noted around monuments in the 3rd quarter 2000 was erroneous, the monuments were in "as-built" condition per follow-up inspection with construction engineer.
- Drainage systems: Acceptable conditions were noted throughout the monitoring period.
- Security: Acceptable conditions were noted throughout the monitoring period.
- Temperature and pressure monitoring equipment (enclosures/hardware): Acceptable
 conditions were noted throughout the monitoring period. Difficulties encountered with
 power, programming and Data Recorder Modules (DRMs) are discussed below.
- Groundwater monitoring wells: Acceptable conditions were noted throughout the monitoring period. The missing "3" label on well 183 has been replaced.
- LCDRS: Pond 8S does not have a LCDRS so this item is not applicable.

Pond 8S Post-Closure Monitoring and Inspection Summary for 2000 February 28, 2001 Page 2

Storm Event Inspections

There were no 25-year, 24-hour storm events or other extraordinary natural events that triggered a storm event inspection during the reporting period.

Temperature Monitoring

No temperature alarms were triggered at the Temperature Monitoring Points (TMPs). The temperature trigger of 22° C was not exceeded at any of the TMPs during the monitoring period. Therefore, no TMP monitoring for soil gas, notification or reporting was required during the monitoring period. Note that the temperature alarm system was designed/installed so that separate signal is sent to the alarm panel board. This system prevented the temperature alarm from being affected by the data logging difficulties described below.

Graphs of the TMP temperature data are presented for the 4th quarter 1999 through 4th quarter 2000 in Attachment A.

As may be expected with the startup of any new electronic system, some difficulties were encountered and actions taken to correct the temperature data logging system as described below and on the quarterly Temperature and Pressure Monitoring Results provided in Attachment A. The 1st quarter 2000 Monitoring Equipment Inspection form noted that the temperature readout panel for T03 was not functional. The panel was replaced with a new panel under manufacturer warranty during the 2nd quarter 2000. Temperature data was not logged from 5/19/00 to 7/11/00 due to a loose ground wire that reset the Data Recorder Modules (DRMs). The problem was fully corrected by 7/18/00.

The logged temperature data for the 3rd quarter were observed to be too low by several degrees C (based on previous observations of subsurface temperature at Pond 8S and a groundwater temperature range of 13° to 15° C at the Pond 8S wells). The temperature DRMs were found to have been incorrectly reprogrammed following the programming loss during the 2nd quarter 2000. The temperature DRMs programming was checked and reprogrammed from a range of 0° to 25° C to the correct range of 0° to 35° C (consistent with the temperature probes' calibrated range). This resulted in an apparent "step" increase in temperature from a range around 12° C at the end of 3rd quarter 2000 to a range around 16° C beginning the 4th quarter 2000. As described above, the temperature data logging signal and programming is independent of the temperature alarm signal and readout and, thus, temperature DRM programming issues did not affect the finding that no temperature alarms were triggered.

Data was not logged at TMPs T01 and T03 during 11/1/00 to 12/31/00 due to DRM failure (the DRMs would not reprogram to log data). The DRMs were sent to the factory for service and were returned to service 1/12/01. Note that the pattern of data that was logged for T01 and T03 during 10/01/00 to 11/1/00 follows the same pattern as the data logged for T04 during the same period. The pattern of data logged for T04 throughout the 4th quarter 2000 is likely a good representation of the data pattern that would have been observed for T01 and T03 during 11/01/00 to 12/31/00. Spare DRMs were purchased and stored on-site to avoid downtime from DRM failures in the future.

The temperature probes were recalibrated (annual recalibration) on 10/30/00 and 10/31/00.

Pond 8S Post-Closure Monitoring and Inspection Summary for 2000 February 28, 2001 Page 3

Pressure Monitoring

No pressure alarms were triggered by the pressure monitoring system. The pressure trigger of 27 inches Hg was not exceeded during the monitoring period. Therefore, no Gas Monitoring Point (GMP) monitoring for soil gas (other than regularly scheduled quarterly GMP monitoring), notification or reporting was required during the monitoring period. Note that the pressure alarm system was designed/installed so that a separate signal is sent to the alarm panel board. This system prevented the pressure alarm from being affected by the pressure data logging difficulties described below.

Graphs of the pressure data are presented for the 4th quarter 1999 through 4th quarter 2000 in Attachment A.

As may be expected with the startup of any new electronic system, some difficulties were encountered and actions taken to correct the pressure monitoring and data logging system as described below and on the quarterly Temperature and Pressure Monitoring Results provided in Attachment A. Pressure data during the 4th quarter 1999 and through 3/23/00 in the 1st quarter 2000 was logged below the lower set-point of 25 inches Hg so the graphs have a "flat line" appearance. At some time after system startup, a power fault apparently reset the pressure DRM to log the output from the sensor as gage pressure (thus logging data as essentially 0 inches Hg). The pressure DRM was correctly reprogrammed on 3/23/00. As described above in the Temperature Monitoring section of this report, due to a loose ground wire that reset the DRMs, pressure data was not logged from 5/19/00 to 7/14/00. The problem was fully corrected by 7/18/00.

A new factory-calibrated pressure sensor was installed on 11/1/00 (annual recalibration) and the original sensor was sent to the manufacturer for factory calibration. The recalibrated sensor was returned and can be used as a calibrated spare.

Soil Gas Monitoring (GMPs)

Soil gas monitoring for hydrogen, phosphine, and hydrogen cyanide was conducted quarterly at the ten GMPs during 4th quarter 1999 through 4th quarter 2000. Overall, soil gases were not detected in eight of the ten GMPs. Initial (peak) detections of hydrogen in GMPs 05 and 07 during the 1st quarter of 2000 are considered false positives because the instrument reading rapidly dropped to zero and hydrogen was not detected in these GMPs in the subsequent 3 quarters. Phosphine and hydrogen cyanide were detected in GMP 07 during 4th quarter 1999 and 3rd and 4th quarter 2000 and GMP 09 during 3rd and 4th quarter 2000. No triggers or actions are prescribed for detection of gases in the GMPs. As discussed above, there were no pressure or temperature alarms triggered during the monitoring period that would indicate problems within the Pond 8S Limit of Final Cover (LFC). FMC/Astaris will continue to evaluate future soil gas monitoring results for trends that may explain the occurrence and implications, if any, of soil gases at GMPs 07 and 09. A summary of the GMP monitoring results by quarter is provided as Attachment B.

The portable gas monitors were factory-calibrated during December 2000 (annual recalibration).

Pond 8S Post-Closure Monitoring and Inspection Summary for 2000 February 28, 2001 Page 4

Cap Drainage Monitoring

No water was pumped from the cap drainage subdrain outlets #1 or #2 during the monitoring period (readings on the totalizing meters were both zero on 9/30/00). Therefore, the total cap drainage / infiltration rate was zero for the monitoring period and required no further evaluation or action. In the future, cap drainage monitoring (reading the totalizing meters) will be conducted during the 4th quarter. The Quarterly Groundcover Inspection form for Pond 8S has been revised to reflect this revision.

Topsoil Monitoring

Topsoil thickness as measured at the topsoil markers was acceptable and no action was required throughout the monitoring period.

Settlement Monitoring

Annual settlement monitoring (survey of permanent settlement monuments) indicated that settlement rates are acceptable at all five monuments. No visual subsidence or seismic events occurred that would have triggered additional settlement monitoring, engineering evaluation or repair during the monitoring period.

Post-Closure Plan Revisions

There were no changes in plant operations or regulations that required revision of the Pond 8S postclosure plan.

TABLE 10-1
Post-Closure Activity Checklist

Post-closure Monitoring/Inspection Activity	Record/Report	Activity	Reporting	Trigger(s)	Action(s)	Closure Plan Reference
		Frequency	Frequency *			
						1
Groundwater monitoring	Quarterly data validation report	Quarterly	Ouesterly	Can IS GW monitoring plan	Can IS OW manitaring plan	Sections 4 & 5; Attachment 10-1
Quarterly monitoring	Quarterly data validation report Statistical evaluation, and Annual	Quarterly	Quarterly	See IS GW monitoring plan	See IS GW monitoring plan	Sections 4 & 5, Attachment 10-1
Annual groundwater assessment	Assessment Report	Annually	Annually	See IS GW monitoring plan	See IS GW monitoring plan	Attachment 10-1
		1				
Quarterly inspections						
Cap and cover	Inspection log	Quarterly	Annually	Visual or electronic indication of degradation or damage	Repair or replace as soon as practical	Section 10
Monuments	Inspection log	Quarterly	Annually			
Drainage systems	Inspection log	Quarterly	Annually			
Security/signs	Inspection log	Quarterly	Annually			
Temperature and pressure monitoring systems	Inspection log	Quarterly	Annually			188
Monitoring wells	Inspection log	Quarterly	Annually			
LCDRS	Inspection log	Quarterly	Annually	Leachate present	Remove leachate	Section 10
25-year, 24-hour storm event inspection	Inspection log	w/in 48-hours	w/ Annual	Same as quarterly	Same as quarterly	Section 10.7
					Notify EPA within 48 hours; monitor TMP	
Temperature monitoring under the cap	Data logger and printout	Continuously	Quarterly	Exceeds 22 degrees C	for H ₂ , PH ₃ , HCN	Attachment 10-2a; Section 1.4.1
Pressure monitoring under the cap	Data logger and printout	Continuously	Quarterly	Exceeds 27 inches Hg	Notify EPA within 48 hours; monitor for H ₂ , PH ₃ , HCN	Attachment 10-2a; Section 1.4.2
			Notify within 48- hours	Pressure under cap exceeds 27 inches of mercury absolute pressure continuously for 1 week and gas concentrations are detected.	Install gas treatment system and convert pressure monitoring system to gas collection w/in 60 days	Attachment 10-2a; Section 1.4.2
Cap drainage monitoring (not applicable Ponds 9E & 8E)	Inspection log	Annually	Annually	See Section 10.9 for decision tree	Evaluate/inspect/repair	Section 10.9
Topsoil monitoring (not applicable Ponds 9E & 8E)	Inspection log	Annually	Recorded only	5-inches below installed thickness at 50 percent of indicators	Add topsoil and revegetate	Section 10.10
Settlement monitoring						
During temporary fill/cap	Survey report	Monthly	Quarterly	Settlement less than 1-inch per year	Install final cap	Section 7.4.7
After final cap	Survey report	Annually	Annually	Exceeds acceptable rates	Engineering evaluation/repair	Sections 7.4.8 and 10.4
Visible subsidence or local seismic event	Survey report	As soon as	Annually	Exceeds acceptable rates	Engineering evaluation/repair	Section 10.4
Figible Subsiderioe of food Solding West		practical				
RCRA regulations/plant operations	Post-closure Plan	60 days	60 days	Operational or regulation changes	Revise the Post-closure Plan	Section 10
Note: * Unless greater or lesser frequency is approved by EP.	Α.					

ATTACHMENT A


Temperature and Pressure Monitoring Results, Quarterly Monitoring Equipment Inspection forms, and Quarterly Groundcover Inspection forms

4th Quarter 2000

Pond 8S Post Closure Temperature and Pressure Monitoring Results

Summary: There is data loss on probes T001 and T003 from 11/1/00 at \sim 09:15 to the end of the quarter due to Data Recorder Module (DRM) failure. Both DRMs were sent to the manufacturer for repair and should be returned the first part of 2001. There is data loss on P001 and T002 from 11/1/00 at \sim 09:15 to 11/19/00 @ \sim 06:57 and from 11/21/00 at 10:00 to 11/26/00 at 07:57. This data loss was due to the DRMs losing their programming. Reprogramming the modules each time fixed the problem. Temperature probe T004 ran without failure during the 4^{th} quarter 2000. All temperatures remained in acceptable bands with no incident of alarms.

Pressure Sensor P001:




Summary Statistics

Number of readings: 13876	
Maximum: 25.91	
Minimum: 25.00	
Mean: 25.47	
Mode: 25.61	
Median: 25.46	

Comments: Pressure is variable across a narrow band. This is consistent with atmospheric pressures logged during this time. Spare factory calibrated pressure sensor installed on 11/01/2000 for annual calibration. Replaced sensor sent to factory for calibration and returned on 12/11/2000.

Temperature Sensor T001:




Summary Statistics

Summary Statistics	
Number of readings: 4513	
Maximum: 16.49	
Minimum: 15.88	
Mean: 16.23	
Mode: 16.23	
Median: 16.23	

Comments: Temperature had risen slowly through a .61-degree range during the period from 10/1/00 to 11/1/00. Annual recalibration of temperature probe conducted on 10/31/2000.

Temperature Sensor T002:




Summary Statistics

Dullillary Dualistics	
Number of readings: 14081	
Maximum: 16.58	
Minimum: 15.57	
Mean: 16.29	
Mode: 16.41	
Median: 16.32	
Minimum: 15.57 Mean: 16.29 Mode: 16.41	

Comments: Temperature had risen until the mid part of November and then started to decrease continually towards the end of the 4th quarter 2000. Temperatures changed within a 1.01-degree range. Annual recalibration of temperature probe conducted on 10/31/2000.

Temperature Sensor T003:




Summary Statistics

Number of readings: 4517	
Maximum: 17.41	
Minimum: 16.71	
Mean: 17.07	
Mode: 17.28	
Median: 17.06	

Comments: Temperature had risen slowly through a .70-degree range from the period 10/1/00 to 11/1/00. Annual recalibration of temperature probe conducted on 10/30/2000.

Temperature Sensor T004:



Summary Statistics

Number of readings: 13163	
Maximum: 17.98	
Minimum: 17.11	
Mean: 17.64	
Mode: 17.76	
Median: 17.67	

Comments: Temperature had risen until the mid part of November and then started to decrease continually towards the end of the 4th quarter 2000. Temperatures changed within a .87-degree range. Annual recalibration of temperature probe conducted on 10/31/2000.

Pond 8S Post Closure Inspection Record Form Quarterly Monitoring Equipment Inspection

Dector: <u>VALERIE BERTI</u> Inspection Item	Signature: <u>Valley</u> Inspection Result
inspection item	* Requires detailed explanation
Temperature Monitoring Wells (TT001, TT00	
Temperature well covers intact and locked?	Acceptable*Unacceptable
Explain Unacceptable Condition:	
all lids are	locked; however, le
TT 003 : -T0 : 0	1 and 1 all th
way down.	
Motor Brief mand	and be rested a
way down. Mote: Boxes need sealed.	oney, our secret.
Groundwater Monitoring Wells (155, 156, 157	, 158, and 183):
Are barrier poles intact?	Acceptable*Unacceptable
Are well covers intact and locked?	Acceptable *Unacceptable
Explain Unacceptable Condition:	
Well # 183 is misser	ng the #3 stiker on
it.	0
	- A = -

Pressure Monitoring Standpipe (P001)	
Standpipe intact?	Acceptable*Unacceptable
Explain Unacceptable Condition:	
Standpipe i	n good condition.
	v-
	A STATE OF THE PROPERTY OF THE
	-2, GM-3, GM-4, GM-5, GM-6, GM-7, GM-8, GM-9,
GM-10)	Acceptable *Unacceptable
Well covers intact and locked?	
Have quarterly monitoring samples been t	aken and logged? Yes *No
Explain Unacceptable Condition:	
Otrly amol	bes.
yerry sample	1 was the good
part of Wecemi	ber.
,	
	×
Temperature & Pressure Alarm Panel	
Alarm sound and red light flash when test	
Panel in acceptable condition?	Acceptable*Unacceptable
Quarterly data downloaded and database u	updated? Yes*No
Explain Unacceptable Condition:	
all data in	down loaded to date
41	and and a deal
the remainder of	f the quarters and
will be down	loaded on gar. 1, 200
TODI 4 TOD.3	Demis as at man
1001 4 1000	Dicinis are ac small
yactures yor	servicing; therefore
no data is bein	in collected for the
lun to	t well-
CARLES INDUSTRIAL AND STATE	

J.	Temperature and Fressure Data Logger Fanei				
	Data logger panel condition? Acceptable*Unacceptable				
	Explain Unacceptable Condition:				
	Panel appears in good condition.				
	- and appears an good concern				
	Settlement Monuments				
	Settlement monuments clear and accessible? Acceptable*Unacceptable				
	Explain Unacceptable Condition:				
	Settlement Monuments are accessible and clear of debris.				
	securer Monuments are accession				
	and clear of debres.				
	Are any repairs or response required?				
5.					
	If a response is required attach a copy of the work order and/or details of the maintenance and repair				
	completed. Do this for each item as needed. Then complete the following for each item.				
	a. Inspection item receiving repair				
	b. Date and Time of completion				
	c. Are repairs acceptable? Yes No				
	d. Inspector				
	e. Signature				

	Pond 8S Post Closure Inspection Record Form
	Quarterly Groundcover Inspection (4th Q1r. 2000)
	☐ Storm Event Inspection
Dat	te: 12/8/00 Time: 10: 18 am
Ins	pector: VALERIE A. BERTI Signature: Valeria A. Buti
	Inspection Item Inspection Result
	* Requires detailed explanation
1	Vegetative Condition (Grass and Ground Cover)
	Is the grass living (root system intact)? Acceptable *Unacceptable
	Is there uniform coverage (no bare spots)? Acceptable *Unacceptable *
	Explain Unacceptable Condition:
	2 2
	are from 2-4 ft. tall. He new
	are from 2-4 ft. tall. He new
	growth since 3rd quarter.
2.	Vegetative Soil Conditions
	No excessive soil erosion? Acceptable *Unacceptable
	No excessive ruts or potholes present? Acceptable*Unacceptable
	No rodent or insect activity
	(i.e., fresh soil piles or holes,) Acceptable*Unacceptable
	Explain Unacceptable Condition:
	~ 10 feet cast of TTOOI there is a
	Spirly new hale a few inches wide
	with mice droppings. Some holes
	in this area were covered last quarter
	Mice trais are suggested.
	The way are my greater.

	Storm water Management
	Are the swales clear of sediment and debris? Acceptable *Unacceptable
	Explain Unacceptable Condition:
5	Small amount of granel in swales, but not enough to inhibit water
55	Small amount of granel in swales,
	but met enough to inhibit water
25	
33	flow.
0.000	Slopes
	No sloughing or tension cracking? Acceptable *Unacceptable
	No excessive channels or washouts? Acceptable*Unacceptable
	Explain Unacceptable Condition:
	To new idea as of usein) on the
24	No meridence of eresion on the slopes since 3rd atr 2000.
3	slopes since 3 Gtr 2000.
	Cap Drainage Monitoring (Annual Check to be performed in 3 rd Quarter)
	Is this the 3 rd quarter of the year? *YesNo
	If 3 rd quarter measure and record volume in subdrain outlet #1
	If 3^{rd} quarter measure and record volume in subdrain outlet #2 N/A
	Total Volume N/A
	Comments:
	NIA = 11st applicable
2	N/A = Not applicable
	N/A = Not applicable
3	N/A = Not applicable
3	N/A = Not applicable

Topsoil Marker	Measurement (inches below nominal installed level)
.1	1/2 "
2	D"
3	<u></u>
4	1/4 "
5	<u> </u>
6	1/4"
7	"14" - Missing a pale for cusy I locating.
more then 4 of the above topsoil mea	surements at 5 inches or more below the installed thickness?
A TOTAL PROPERTY OF THE PROPER	*Yes No
Comments:	
1	3rd atr 2000, the only
since	3 atr 2000, the only
Toposil Mar	ker with a change in
verosim las	el 4500 #3 which w
1 1/1	t a l"
from 1/2"	10 21.
<i>V</i>	
Security Systems	
Fencing continuous and intact?	Acceptable*Unacceptable
Gate locks present and functional?	Acceptable *Unacceptable
Monitoring camera functional?	Acceptable *Unacceptable
	proaches that read "Danger- Unauthorized Personnel Keep Out"
	Acceptable*Unacceptable
in English only?	AcceptableTonacceptable
Explain Unacceptable Condition:	
Had to ele	ear large weeds from
772	

Security systems are intact.

6. Cap Erosion Monitoring


8.	Are any repairs or response required?	*Yes No
	If a response is required, attach a copy of the work order and	or details of the maintenance and
	repair completed. Do this for each item as needed. Then com	plete the following for each item:
a.	Inspection item receiving repair	
b.	Date and Time of completion	
c.	Are repairs acceptable? Yes No	
d.	. Inspector	
e.	Signature	

3rd Quarter 2000

Pond 8S Post Closure Temperature and Pressure Monitoring Results

Summary: All temperatures remained in acceptable bands with no incident of alarms. There is data loss on pressure from start of quarter to July 17th and all temperatures from start of quarter to July 10th and 11th, due to a loose ground wire. The follow up programming issues were resolved by July 18th, 2000. All data from that date is complete and without known errors.

Pressure Sensor P001:




Summary Statistics

Number of readings: 10462	
Maximum: 25.70	
Minimum: 25.00	
Mean: 25.43	
Mode: 25.46	
Median: 25.45	

Comments: Pressure is variable across a narrow band. This is consistent with atmospheric pressures logged during this time.

3rd Quarter 2000 (Cont.)

Temperature Sensor T001:




Summary Statistics

Summing Summer	
Number of readings: 11695	
Maximum: 11.44	
Minimum: 10.25	
Mean: 10.79	
Mode: 10.41	
Median: 10.75	

3rd Quarter 2000 (Cont.)

Temperature Sensor T002:




Summary Statistics

Number of readings: 11837	
Maximum: 11.44	
Minimum: 10.19	
Mean: 10.75	
Mode: 10.47	
Median: 10.72	

3rd Quarter 2000 (Cont.)

Temperature Sensor T003:




Summary Statistics

Summary Statistics	
Number of readings: 11837	
Maximum: 12.03	
Minimum: 10.88	
Mean: 11.39024	
Mode: 11.03	
Median: 11.34	

3rd Quarter 2000 (Cont.)

Temperature Sensor T004:



Summary Statistics

֡֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜

Pond 8S Post Closure Inspection Record Form Quarterly Monitoring Equipment Inspection

Inspection Item Inspection Result requires detailed explaination 1. Temperature Monitoring Wells (TT001, TT002, TT003, TT004) Temperature well covers intact and locked? Exceptable Inspection Result requires detailed explaination Acceptable Inspection Result requires detailed explaination Inspection Result requires detailed explaination Inspection Result requires detailed explaination Inspection Result requires detailed explaination	
1. Temperature Monitoring Wells (TT001, TT002, TT003, TT004) Temperature well covers intact and locked? Explain Unacceptable Condition:	
Temperature well covers intact and locked? Explain Unacceptable Condition:	
Explain Unacceptable Condition:	
Explain Unacceptable Condition:	
Everything appears to be intact.	
2. Pressure Monitoring Standpipe (P001)	
Standpipe intact and locked? Acceptable *Unacceptable	
Explain Unacceptable Condition,	
Pressure monitoring standpipe in good	
Condition.	

	Soil Gas Monitoring Wells (GM-1,GM-2, GM-3, GM-4, GM-5, GM-6, GM-7, GM-8, GM-9,
SM-	10)
	Well covers intact and locked? Acceptable **Unacceptable
	Have quarterly monitoring samples been taken and logged? Yes
	Explain Unacceptable Condition:
	Rubber liner is slightly exposed by ground pair water well 6M8. "Reed to watch - if additional
	Kubber cliner is slightly exposed by ground pain
2	water well 6M8. Need to watch - if additional
	material becomes exposed, may need to
	add cover at this area.
ii.	
	Temperature & Pressure Alarm Panel
	Alarm sound and red light flash when tested? Acceptable *Unacceptable
	panel in acceptable condition? Acceptable Acceptable Acceptable Chacceptable
	Quarterly data downloaded and database updated? Yes
	Quarterry data downloaded and database updated:
	Explain Unacceptable Condition:
*	not and of quarter yet will download data or
	10/1/20
9	19/1/00 -
7	
	Temperature and Pressure Data Logger Panel
	Data logger panel condition? Acceptable nacceptable
	Explain Unacceptable Condition:
	Panel appears in good condition.
í	

6.	Settlement Monuments
	Settlement monuments clear and accessible? Acceptable
	Explain Unacceptable Condition:
	@ Sm #2 - possible erosion ground base.
	Exposed 2" on SE side.
}	OF TOR @ Sm # 5 3" to 4" passible settlement
	Acte: These observations were incorrect. Poured
	concrete bases were in as built condition
	confirmed by Reb-Hartman @ FMC.
7.	Are any repairs or response required?
	If a response is required attach a copy of the work order and/or details of the maintenance and repair
	completed. Do this for each item as needed. Then complete the following for each item.
	a. Inspection item receiving repair
	b. Date and Time of completion N/A
	c. Are repairs acceptable Yes No N/A
	d. Inspector/A
	e. Signature N/A

N/A = Not applicable.

☐ Storm Event Inspection Date: 9/30/00 Inspector: U.B. (VALERIE BERTI) Signature: Valerie Berti Inspection Item Inspection Result * Requires detailed explanation 1. Groundwater Monitoring Wells (155, 156, 157, 158, and 183): Acceptable *Unacceptable Are barrier poles intact? Acceptable *Unacceptable Are well covers intact and locked? Explain Unacceptable Condition: Groundwater Well #183 is missing the sticker. 2. Vegetative Condition (Grass and Ground Cover) Acceptable *Unacceptable Is the grass living (root system intact)? Acceptable V *Unacceptable Is there uniform coverage (no bare spots)? Explain Unacceptable Condition:

Pond 8S Post Closure Inspection Record Form

☑ Quarterly Groundcover Inspection

3.	Vegetative Soil Conditions		
	No excessive soil erosion? Acceptable *Unacceptable		
	No excessive ruts or potholes present? Acceptable *Unacceptable		
	No rodent or insect activity		
	(I.e., fresh soil piles or holes,) Acceptable *Unacceptable		
	Explain Unacceptable Condition:		
	Near Sm #2 there is evidence of mice +		
	small heles a the base. Minor erasion.		
	Base is exposed, East of TTOO, there are		
	two gopher heles. (~10 ft apart.) 30' west of		
	TT004 evidence of droppings. Holes indicate		
	above are only a few inches wide.		
	O D		
4.	Storm Water Management		
	Are the swales clear of sediment and debris? Acceptable *Unacceptable		
	Explain Unacceptable Condition:		
	There is minor quantities of gravel		
	in the swale; however flow is		
	not affected.		
	Statement of the statem		
	3 		
5.	Slopes		
	No sloughing or tension cracking? Acceptable*Unacceptable		
	No excessive channels or washouts? Acceptable *Unacceptable		
	Explain Unacceptable Condition:		
	Hear the south cap there is some		
	soil exposed siving a potential for		
	welly to losm I will know and		
	The same of the sa		
	Leye Th.		

6. Cap Drainage Monitorin	g (Annual Check to be performed in	3 rd Quarter)
Is this the 3rd quarter of th	e year?	*Yes No
If 3rd quarter measure and	record volume in subdrain outlet #1	0
	record volume in subdrain outlet #2	6
50)	Total Volume	0
Comments:		
		11. 11+
_ au svalue	2) un une sus	dian onless
were ser	in the sub	
0		
7. Cap Erosion Monitoring Perform and record the following	lowing topsoil loss measurements	
1 CHOIN and 1000Id the 101		
Topsoil Marker	Measurement (inches be	elow nominal installed level)
ī	1/2 "	
2	0 "	
3	1/2 "	
4	1/4 "	
5	0 "	
6	1/4 "	
	1/11 "	
7		
Are more then 4 of the above to	opsoil measurements at 5 inches or more	e below the installed thickness?
	*Yes No	
Comments:		
None		
	•	
- 2		


er.	-3	
	(A)	
	in English only? Explain Unacceptable Condition:	Acceptable *Unacceptable Acceptable *Unacceptable Acceptable *Unacceptable acceptable *Unacceptable tes that read "Danger- Unauthorized Personnel Keep Out" Acceptable *Unacceptable are *Unacceptable
8	9. Are any repairs or response required? If a response is required, attach a copy of the completed. Do this for each item as needed. a. Inspection item receiving repair a. Date and Time of completion b. Are repairs acceptable? Yes	read testing a little for the first of source entering the first state of the first state of section is set in
	b. Are repairs acceptable? Yes c. Inspector	_NoN/A

2nd Quarter 2000

Pond 8S Post Closure Temperature and Pressure Monitoring Results

Summary: All temperatures and pressure remained in acceptable bands. Data recorded from 01 April 2000 to 18 May 2000. Data from May 19th to end of quarter was lost due to a loose ground wire. The wire caused surges that erased the programming and data from the DRM's in the panel at the pond. The problem was corrected and the system is working as designed.

Pressure Sensor P001:




Summary Statistics

Number of readings: 6855	
Maximum: 25.71	
Minimum:25	
Mean: 25.32864	
Mode: 25.29	
Median: 25.31	

Comments: Pressure fluctuated within a small band and was consistent with local barometric pressure during the same period. There is no indication of any pressure abnormalities.

2nd Quarter 2000 (Cont.)

Temperature Sensor T001:



Summary Statistics:


Number of Readings: 6495	
Maximum: 11.06	
Minimum: 10.25	
Mean: 10.655	
Median: 10.63	
Mode: 10.53	

Comments:

Temperature decline this quarter is consistent with the other 3 temperature legs. There is a gap of no data from May 18th to the end of the quarter. This is due to a loose grounding wire on the pressure probe connections causing surges, which have led to all DRM's loosing data and programming. The problem has been corrected.

2nd Quarter 2000 (Cont.)

Temperature Sensor T002:




Summary Statistics:

Number of readings: 6851	
Maximum: 11	
Minimum: 10.22	
Mean: 10.54	
Median: 10.5	
Mode: 10.34	

Comments: Temperature decline this quarter is consistent with the other 3 temperature legs. There is a gap of no data from May 18th to the end of the quarter. This is due to a loose grounding wire on the pressure probe connections causing surges, which have led to all DRM's loosing data and programming. The problem has been corrected.

2nd Quarter 2000 (Cont.)

Temperature Sensor T003:




Summary Statistics:

Number of readings: 6851	
Maximum: 11.91	
Minimum: 11.03	
Mean: 11.41	
Median: 11.38	
Mode: 11.22	

Comments: Temperature decline this quarter is consistent with the other 3 temperature legs. There is a gap of no data from May 18th to the end of the quarter. This is due to a loose grounding wire on the pressure probe connections causing surges, which have led to all DRM's loosing data and programming. The problem has been corrected.

Temperature Sensor T004:



Summary Statistics:

Number of readings: 6851	
Maximum: 12.34	
Minimum: 11.47	
Mean: 11.858	
Median: 11.84	
Mode: 11.72	

Comments: Temperature decline this quarter is consistent with the other 3 temperature legs. There is a gap of no data from May 18th to the end of the quarter. This is due to a loose grounding wire on the pressure probe connections causing surges, which have led to all DRM's loosing data and programming. The problem has been corrected.

Pond 8S Post Closure Inspection Record Form Quarterly Monitoring Equipment Inspection

Da	te: (7/05/2000 Time: 12:35 Inspector: Just S. Shokes
	Inspection Item Inspection Result * requires detailed explaination
	Temperature Monitoring Wells (TT001, TT002, TT003, TT004)
	Temperature well covers intact and locked? Acceptable *Unacceptable Explain Unacceptable Condition:
	OILED ALL Lockes, Exposers to clements makes
	the hard to operate once a quarter.
	All contacts appear intent inside boxes.
	Pressure Monitoring Standpipe (P001)
	Standpipe intact and locked? Acceptable *Unacceptable
	Explain Unacceptable Condition:
	condition.

3.	Soil-Gas Monitoring Wells (GM-1,GM-2, GM-3,	GM-4, GM-5, GM-	6, GM-7,	GM-8, GM-9,
GI	M-10)			
	Well covers intact and locked?	Acceptable X	*Unacc	eptable
	Have quarterly monitoring samples been taken and le	egged?	Yes	*No <u>X</u>
	Explain Unacceptable Condition:			
	GAS samples are schedul	es,		
4.	Temperature & Pressure Alarm Panel			¥!
	Alarm sound and red light flash when tested?	Acceptable ×	*Unacc	eptable
	panel in acceptable condition?	Acceptable 🔀	*Unacc	eptable
	Quarterly data downloaded and database updated?		Yes ×	*No
	Explain Unacceptable Condition:			
	Parel is in good co.	T stra	Ø0 ?	Dirtri
	1 anel 15 m 3000 Con	ar strilled .	113	
	neter is working.			
	6			
_				7/1
5.	Temperature and Pressure Data Logger Panel Data logger panel condition?	A coomtable X	*I I	ceptable
		Acceptable /-	_ *Ollacc	eptable
	Explain Unacceptable Condition:			
	Panel is in good	shape.		
	9			
	<u> </u>			

Settlement monuments clear and accessible? Acceptable *Unacceptable
Explain Unacceptable Condition:
Simlar to the cap erossion markers
these smaller markers are difficult to
find in the vegitative covering. I will
Look into a flag marking system for
future inspections.
Are any repairs or response required? *Yes No _X_
If a response is required attach a copy of the work order and/or details of the maintenance and repair
completed. Do this for each item as needed. Then complete the following for each item.
a. Inspection item receiving repair
b. Date and Time of completion
c. Are repairs acceptable Yes \sqrt{A} No
d. Inspector

6. Settlement Monuments

7.

e. Signature

Pond 8S Post Closure Inspection Record Form ✓ Quarterly Groundcover Inspection □ Storm Event Inspection

Da	te: 07/05/2000 Time:	12:35
Ins	pector: Juel 5. Shokes Signat	ure: Jacks. Shahn
	Inspection Item	Inspection Result * requires detailed explaination
1.	GroundWater Monitoring Wells (155, 156, 157, 158	s, and 183):
	Are barrier poles intact?	Acceptable *Unacceptable
	Are well covers intact and locked?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
Si .	NONE.	
	(
	Andrew Comments of the Comment	
2.	Vegetative Condition (Grass and Ground Cover)	
A. 18	Is the grass living (root system intact)?	Acceptable _x_ *Unacceptable
	Is there uniform coverage(no bare spots)?	Acceptable X *Unacceptable
	Explain Unacceptable Condition:	
	Uniform coverage. Most pla	at heturen 2-4 ft tall.
	There are no bare spots	. Spacing between
	plants is thinner in	some areas leaving
	about 10% uncovered. 6	iven the protose growth
	this season it should be loo	

3.	Vegetative Soil Conditions	
	No excessive soil erosion?	Acceptable _× *Unacceptable
	No excessive ruts or potholes present?	Acceptable *Unacceptable
	No rodent or insect activity	
-	(i.e., fresh soil piles or holes,)	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	The soil is Supporting	ig lish plant growth. The
		providing a rain break.
		s of errosion. There are
		Pales III veri
	grasshoppers and butter	erflies but no signs of
	roduts birds or ot	or animal lofe,
	,	
4.	Storm Water Management	
355	Are the swales clear of sediment and debris?	Acceptable _x *Unacceptable
	Explain Unacceptable Condition:	Acceptable
		at gravel has washed
	into the smale, not	erough to affect flow.
	These will be swept	out the Ax before next
	quarter for good h	9
	2	- 100 star 3
	ACTUAL CONTRACTOR OF THE PROPERTY OF THE PROPE	THE CO. THE STREET OF THE PROPERTY OF THE PROP
5.	Slopes	
	No sloughing or tension cracking?	Acceptable*Unacceptable
	No excessive channels or washouts?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	Slopes are in	good condition with
	no detectible de	good condition with
		2cs,

6.	Cap Drainage Monitoring (Annual	I Check to be performed in 3rd	Quarter)
	Is this the 3rd quarter of the year?		*Yes No _×
	If 3rd quarter measure and record volu	ume in subdrain outlet #1	~/A
	If 3rd quarter measure and record volu	ume in subdrain outet #2	
		Total Volume	
	Comments:		
	NONE.		
	·		
	1 		
			u de la composição de
7.	Cap Erosion Monitoring		
7.	Perform and record the following tops	soil loss measurements	
	Topsoil Marker	Measurement (inches below	w nominal installed level)
	===		
	1		
	2		
	3	4:	
	4		
	5	<u> </u>	
	6		
	7	/	
۸			14
Ale	more then 4 of the above topsoil meas		elow the installed thickness?
	Commentar	*Yes No _X	
	Comments:	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	These muskers	have become	very difficult
	to find in t	The new folia	acre, I will look
	into the poles		
		701 00210	52 402 Divic
	inspections.	······································	to the second se


8.	Security Systems		
	Fencing continous and intact?	Acceptable	*Unacceptable
	Gate locks present and functional?	Acceptable >	*Unacceptable
	Monitoring camera functional?	Acceptable 😕	*Unacceptable
	Signs posted and visible from all approach	nes that read "Danger- Unauthor	ized Personnel Keep Out"
	in English only?	Acceptable ×	*Unacceptable
	Explain Unacceptable Condition:		
	Security systems a	re intact.	
		·	
0	A		***
	Are any repairs or response required?		*Yes No _X
	a response is required, attach a copy of the		I TO THE COMMENT OF THE ANALYSIS OF THE PARTY OF THE PART
	ompleted. Do this for each item as needed.	i Ze v	each item:
a.			
a.	Date and Time of completion	~/14	
b.	Are repairs acceptable? Yes ~/u	1_ No	
c.	1		
d.	i i		

1st Quarter 2000

Pond 8S Post Closure Temperature and Pressure Monitoring Results

Summary: All Temperatures remained in acceptable bands with no incidence of alarms. The Pressure gage for P001 was replaced and is working according to plan. The temperature module suffered a Y2K glitch and had dates from 1989. The data is corrected for date and the DRM has been reprogrammed to the correct date.

Pressure Sensor P001:




Summary Statistics

Number of readings: 13007	
Maximum: 25.63	
Minimum:25	
Mean: 25.034	
Mode: 25.0	
Median: 25.0	

Comments: Pressure readings initially stuck on 25 due to incorrect pressure gage. The correct gage was installed on 3/23/00 at 13:50. Pressure is now responding according to design.

Temperature Sensor T001:




Summary Statistics:

Swilliam J Swillswitz.	
Number of Readings: 10815	
Maximum: 13.16	
Minimum: 11.03	
Mean: 11.9284	
Median: 11.91	
Mode: 11.91	

Comments: Temperature decline this quarter is consistent with the other 3 temperature legs. There is a gap of no data from 04 JAN 2000 to 19 JAN 2000. This is from reprogramming needed due to an Y2K glitch that reset the date in the DRM to 1989. The DRM has been reprogrammed and the data corrected for dates.

Temperature Sensor T002




Summary Statistics:

Number of readings: 13007	
Maximum: 13.13	
Minimum: 10.91	
Mean: 11.9998	
Median: 12	
Mode: 11.78	

Comments: Temperature decline this quarter is consistent with the other 3 temperature legs.

Temperature Sensor T003




Summary Statistics:

Number of readings: 13006	
Maximum: 14	
Minimum: 11.78	
Mean: 12.90	
Median: 12.91	
Mode: 12.69	

Comments: See comments on Temperature T002.

Temperature Sensor T004



Summary Statistics:

Summary Statistics.	
Number of readings: 13007	
Maximum: 14.38	
Minimum: 12.22	
Mean: 13.32	
Median: 13.31	
Mode: 13.78	

Comments: See comments on Temperature T002.

Pond 8S Post Closure Inspection Record Form Quarterly Monitoring Equipment Inspection

Dat	te: 03/31/2000 Time: 10:00	Inspector: Joel S. Shokes
		Signature: Acel S. 5 bah
	Inspection Item	Inspection Result * requires detailed explaination
1.	Temperature Monitoring Wells (TT001, T	T002, TT003, TT004)
	Temperature well covers intact and locked?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	NONE -	
2.	Pressure Monitoring Standpipe (P001)	
	Standpipe intact and locked?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	New pressure gauge	installed 23 mar 2000 to
	correct pressure reads	ngs. New gauge works as
	designed. The old	gauge reads gauge
	pressure, the ne	gauge reads gauge w one reads absolute
	pressure.	

~~	50n Gas monitoring wens (GM-1,GM-2, GM-3, GM-4, GM-5, GM-6, GM-7, GM-8, GM-9,
Gľ	M-10)
	Well covers intact and locked? Acceptable *Unacceptable
	Have quarterly monitoring samples been taken and logged? Yes*No*
	Explain Unacceptable Condition:
	Quartoy gas samples are scheduled for
	Quartoy gas samples are scheduled for later this afternoon.
	(20.0)
4.	Temperature & Pressure Alarm Panel
*•	Alarm sound and red light flash when tested? Acceptable *Unacceptable
	panel in acceptable condition? Acceptable *Unacceptable *Unacceptable
	Quarterly data downloaded and database updated? Yes *No
	State of the state
	Explain Unacceptable Condition:
	NONG
	<u>→</u>
5.	Temperature and Pressure Data Logger Panel
	Data logger panel condition? Acceptable*Unacceptable
	Explain Unacceptable Condition:
	Called #2012 through closed lights for the contribution of the property of the called th
	Temperature digital meter is not tractional to
	Temperature Digital meter is not functional for TODS. This Does NOT affect Data loggina
	or monitoring functions.

 $t_{\mathcal{J}}$

0

	Set	ttlement monuments clear and accessible? Acceptable *Unacceptable
	Ex	plain Unacceptable Condition:
		NONE
	0	
	S)
		V
7.	Ar	re any repairs or response required? *Yes No
	If a	response is required attach a copy of the work order and/or details of the maintenance and repair
	con	npleted. Do this for each item as needed. Then complete the following for each item.
	a.	Inspection item receiving repair TOO3 Digital Meter
	b.	Date and Time of completion
	c.	Are repairs acceptable Yes No
	d	Inspector

6. Settlement Monuments

Signature _

Pond 8S Post Closure Inspection Record Form ✓ Quarterly Groundcover Inspection ☐ Storm Event Inspection

Da	te: 03/31/2000 Time: 10'.00
Ins	pector: Joel S. Sholles Signature: Joul S. She
	<u>Inspection Item</u> * requires detailed explaination
1.	GroundWater Monitoring Wells (155, 156, 157, 158, and 183):
	Are barrier poles intact? Acceptable *Unacceptable
	Are well covers intact and locked? Acceptable *Unacceptable
	Explain Unacceptable Condition:
	NONE
	V
2	Vocatative Condition (Const and Constal Constal
2.	Vegetative Condition (Grass and Ground Cover) Is the grass living (root system intact)? Acceptable *Unacceptable
	Is there uniform coverage(no bare spots)? Acceptable *Unacceptable *Una
	Explain Unacceptable Condition:
	It has been dry through the 1st Quarter As
	spring rains have not begun yet. The soil
	shows uniform AND shallow (1-Zinches) wacking
	dre to dryness. Seeds have not begun to
	germinate. Seed cover is uniform and complete

3.	Vegetative Soil-Conditions
	No excessive soil erosion? Acceptable*Unacceptable
	No excessive ruts or potholes present? Acceptable *Unacceptable
	No rodent or insect activity
	(i.e., fresh soil piles or holes,) Acceptable *Unacceptable
	Explain Unacceptable Condition:
	uniform and shallow cracking due to dryness.
	This does not affect cap integrity.
	The state of the s
4.	Storm Water Management
	Are the swales clear of sediment and debris? Acceptable *Unacceptable
	Explain Unacceptable Condition:
	NONE
	V
5.	Slopes
	No sloughing or tension cracking? Acceptable*Unacceptable
	No excessive channels or washouts? Acceptable *Unacceptable
	Explain Unacceptable Condition:
	NONE

Is this the 3 rd quarter of the year? If 3 rd quarter measure and record volume in subdrain outlet #1 If 3 rd quarter measure and record volume in subdrain outlet #2 Total Volume Comments: *YesNo/A Total Volume Comments: *YesNo/A Total Volume Comments: *YesNo/A *Yes	6.	Cap Drainage Monitoring (A	Annual Check to be performed in 3°	Quarter)	
If 3rd quarter measure and record volume in subdrain outet #2 Total Volume Comments: Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1 2 3 4 5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		Is this the 3 rd quarter of the year	ar?	*Yes No	
Total Volume Comments: Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1 2 3 4 5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		If 3rd quarter measure and reco	rd volume in subdrain outlet #1	~/A	
7. Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1		If 3rd quarter measure and reco	rd volume in subdrain outet #2		
7. Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level)			Total Volume		
7. Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1		Comments:			
7. Cap Erosion Monitoring Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1		NANE -			
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1				1	
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1					
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1					_
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1					
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1		Y			
Perform and record the following topsoil loss measurements Topsoil Marker Measurement (inches below nominal installed level) 1					
1	7.	Cap Erosion Monitoring Perform and record the followi	ng topsoil loss-measurements		
2 3 4 5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No✓ Comments:		Topsoil Marker	Measurement (inches below	nominal installed level)	
3 4 5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		1	Ø		
4 5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		2	Ø		
5 6 7 Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		3			
Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		4			
Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		5			
Are more then 4 of the above topsoil measurements at 5 inches or more below the installed thickness? *Yes No Comments:		6			
*Yes No		7			
*Yes No			e		
Comments:	Are	e more then 4 of the above topso	7.94	low the installed thickness?	
			*Yes No		
NONE		Comments:			
		NONE			
)		
3		7			

8	Security Systems			
	Fencing continous and intact?	Acceptable	*Unacc	eptable
	Gate locks present and functional?	Acceptable	*Unacc	eptable
	Monitoring camera functional?	Acceptable	*Unacc	eptable
	Signs posted and visible from all approa	ches that read "Danger- Una	uthorized Perso	nnel Keep Out"
	in English only?	Acceptable	✓ *Unacc	eptable
	Explain Unacceptable Condition:			
	Sign by #1 i # Z but still legible	Soil ges well	show	noest
	but +111 lasible	from street	antsino	of ferce
	3111 1831011			0 - 3
	N			
				1
9.	Are any repairs or response required?		*Yes	No
If	a response is required, attach a copy of the	he work order and/or details	of the maintena	nce and repair
C	empleted. Do this for each item as needed	Then complete the followin	g for each item	•)
	miprotes. Do-this-for-cach nette as-necues	- Then complete me followin	Proz orom-riour	•
a.			P 101 0102 M	•
	Inspection item receiving repair	~0~6		•
a.	Inspection item receiving repair Date and Time of completion	~/A		•
a. a.	Inspection item receiving repair Date and Time of completion Are repairs acceptable? Yes	~/A /4 No <u>~/A</u>		•


 $L \ge$

4th Quarter 1999

Pond 8S Post Closure Temperature and Pressure Monitoring Results

Summary: All Temperatures remained in acceptable bands with no incidence of alarms. Pressure readings appear locked in at the bottom end of the pressure range. This anomaly is being investigated. Data retrieval started on 10-29-1999 coinciding with turnover of the pond for post closure monitoring. From 11-08-99 to 11-20-99 data was not recorded. This was due to an unsuccessful program change attempting to better optimize data gathering.

Pressure Sensor P001:




Summary Statistics

Number of readings: 7807	
Maximum: 25.0	
Minimum: 24.94	
Mean: 24.99	
Mode: 25.00	
Median: 25.00	

Comments: Pressure readings initially varied in a 24.96 to 25.00 in Hg range. They appear locked in at 25.0 without variance since 11-22-99. Jim Cameron of Bechtel is investigating the type of sensor used to measure the pressure as a source of this problem.

Temperature Sensor T001:




Summary Statistics:

Number of Readings: 7838	
Maximum: 14.09	
Minimum: 13.06	
Mean: 13.58	
Median: 13.59	
Mode: 13.62	

Comments:

Temperature decline this quarter is consistent with the other 3 temperature legs. It is winter and the ambient temperature above the cap has declined. This appears to be reflected in the temperature charts for all the temperature monitors.

Temperature Sensor T002:




Summary Statistics:

Number of readings: 7687	
Maximum: 14.06	
Minimum: 13.03	
Mean: 13.56	
Median: 13.56	
Mode: 13.62	

Comments: See comments on Temperature T001.

Temperature Sensor T003:




Summary Statistics:

Summary Statistics.	
Number of readings: 8050	
Maximum: 14.91	
Minimum: 13.91	
Mean: 14.44	
Median: 14.47	
Mode: 14.47	

Comments: See comments on Temperature T001.

Temperature Sensor T004:



Summary Statistics:

Builling Buildies.	
Number of readings: 7646	
Maximum: 15.22	
Minimum: 14.25	
Mean: 14.75	
Median: 14.75	
Mode: 14.84	

Comments: See comments on Temperature T001.

Pond 8S Post Closure Inspection Record Form Quarterly Monitoring Equipment Inspection

Da	te: 16 DEC 99	Time: 12.30	Inspector: Joel 5.5 hoky
			Signature: Jul S-Shehm
	Inspection Ite	<u>m</u>	Inspection Result * requires detailed explaination
1.	Temperature Monitoring	Wells (TT001, TT002,	TT003, TT004)
	Temperature well covers int	tact and locked?	Acceptable*Unacceptable
	Explain Unacceptable Cond	dition:	
	LADGED COU	ers with a	read stack permanent
	MARKER		
2.	Pressure Monitoring Stand	dpipe (P001)	
	Standpipe intact and locked	?	Acceptable*Unacceptable
	Explain Unacceptable Cond	dition:	
	NONE		
		9	

3.	Soil Gas Monitoring Wells (GM-1,GM-2, GM-3,	GM-4, GM-5, GM-6, GM-7, GM-8, GM-9,
GN	1-10)	
	Barrier poles intact?	Acceptable *Unacceptable
	Well covers intact and locked?	Acceptable*Unacceptable
	Have quarterly monitoring samples been taken and lo	gged? Yes *No/
	Explain Unacceptable Condition:	
	LABELED MONITOR WELLS	
	in Q+AD QUARTER	edules for Lastwee
ı.	Temperature & Pressure Alarm Panel	
	Alarm sound and red light flash when tested?	Acceptable *Unacceptable
	panel in acceptable condition?	Acceptable *Unacceptable
	Quarterly data downloaded and database updated?	Yes *No/
	Explain Unacceptable Condition:	
	Scheduled for 15t is	by DATA DOWNload
	scheduled for 15t u	seek in January to
	capture full QUARTER	
	The second of th	
	Temperature and Pressure Data Logger Panel	
	Data logger panel condition?	Acceptable*Unacceptable
	Explain Unacceptable Condition:	
	NONE	

6.	Settlement Monuments	
	Settlement monuments clear and accessible?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	EABER Settlement monument	to with mean stick
7.	Are any repairs or response required?	*Yes No
	If a response is required attach a copy of the work order are completed. Do this for each item as needed. Then complete	
	a. Inspection item receiving repair	
	b. Date and Time of completion NONE	
	c. Are repairs acceptable Yes \sqrt{A} No \sqrt{A}	
	d. Inspector	
	S:	

Pond 8S Post Closure Inspection Record Form

✓ Quarterly Groundcover Inspection

□ Storm Event Inspection

Da	nte:_ SDEC99_	Time: 12:30
Ins	spector: Joel S. Sholles	Signature: Jack Shohn
	Inspection Item	Inspection Result * requires detailed explaination
1.	GroundWater Monitoring Wells (155, 15	6, 157, 158, and 183):
	Are barrier poles intact?	Acceptable *Unacceptable
	Are well covers intact and locked?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	Well # 183 is w	issing the #3 from its.
	Lubel.	
	# 156 = 183 Are or	Aside of the RCRA fence
	area on south road	
2.	Vegetative Condition (Grass and Ground	Cover)
	Is the grass living (root system intact)?	Acceptable *Unacceptable
	Is there uniform coverage(no bare spots)?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	Vegitation hasn'	t begun to grow,
	Seed MATERIAL L	nas unstorm coverage
	·	

3.	Vegetative Soil Conditions	
	No excessive soil erosion?	Acceptable *Unacceptable
	No excessive ruts or potholes present?	Acceptable *Unacceptable
	No rodent or insect activity	
	(i.e., fresh soil piles or holes,)	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	_ NoNE	
	Samuel Water Management	
4.	Storm Water Management Are the swales clear of sediment and debris?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	Acceptable V Onacceptable
		V .
	There is SNOW in	the swales, Loss
	the Yzinch Light	powlery snow similar
	a second	area. Doesnot Look
		result drainage in an
	10 2004	Ü
-2		
5.	Slopes	
	No sloughing or tension cracking?	Acceptable *Unacceptable
	No excessive channels or washouts?	Acceptable *Unacceptable
	Explain Unacceptable Condition:	
	NONE	
		3
	mental of the second se	

6.	Cap Drainage Monitoring	(Annual Check to be performed in 3rd	Quarter)
	Is this the 3rd quarter of the	year?	*Yes No
	If 3rd quarter measure and re	ecord volume in subdrain outlet #1	N/A
	If 3rd quarter measure and re	~/A	
		Total Volume	NA
	Comments:		
	~0~F		
	~5~2	18	

7.	Cap Erosion Monitoring	owing topsoil loss measurements	
	Perform and record the folic	owing topson loss measurements	
	Topsoil Marker	Measurement (inches belo	w nominal installed level)
	1		
	2		×
	3		
	4		
	5		
	6	O	
	7	0	*
Are	e more then 4 of the above to	psoil measurements at 5 inches or more t	pelow the installed thickness?
		*Yes NoNo	
	Comments:		
		1	
	- Agraced	. LABELED MARKERS	75-01 to TS-07
	For cons	istercy of future	measurements
	,		

٤.

Ø	(AB)			
X. 5	Security Systems			
()	Fencing continous and intact?	Acceptable	*Unacc	eptable
(Gate locks present and functional?	Acceptable	*Unacc	eptable
1	Monitoring camera functional?	Acceptable	*Unacc	eptable
5	Signs posted and visible from all approache	s that read "Danger- Unautho	rized Perso	nnel Keep Ou
i	n English only?	Acceptable	*Unacc	eptable
I	Explain Unacceptable Condition:			
	NONE			
				X X
-				
-				
40				
9. A	re any repairs or response required?		*Yes	No _
Ifa	response is required, attach a copy of the v	vork order and/or details of th	e maintena	nce and renair

COII	apleted. Do this for each item as needed. The	The second second		1:
a.	Inspection item receiving repair	\sim /A		
a.	Date and Time of completion	N/A	è	
b.	Are repairs acceptable? Yes \sqrt{A}	No N/A		
c.	Inspector ~/A			
d.	Signature ~/A			

 S^{j}

ATTACHMENT B

Summary of Soil Gas Monitoring Results

Pond 8S - Summary or soil Gas Monitoring Results 1999

Soil Gas	4th Quarter 1999									
Monitoring Locations	H2 (ppm) Peak	H2 (ppm) Steady State	PH3 (ppm) Peak	PH3 (ppm) Steady State	HCN (ppm) Peak	HCN (ppm) Steady State				
0007SG01	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG02	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG03	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG04	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG05	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG06	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG07	20.00	20.00	0.046	0.037	16.80	16.80				
0007SG08	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG09	0.00	0.00	0.00	0.00	N/A	N/A				
0007SG10	0.00	0.00	0.00	0.00	N/A	N/A				

Pond 8S - Summary of Soil Gas Monitoring Results 2000

Soil Gas			1st Qu	arter 2000		2nd Quarter 2000						
Monitoring Locations	H2 (ppm) Peak	H2 (ppm) Steady State	PH3 (ppm) Peak	PH3 (ppm) Steady State	HCN (ppm) Peak	HCN (ppm) Steady State	H2 (ppm) Peak	H2 (ppm) Steady State	PH3 (ppm) Peak	PH3 (ppm) Steady State	HCN (ppm) Peak	HCN (ppm) Steady State
0007SG01	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG02	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG03	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG04	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG05	* 50.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG06	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG07	* 50.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG08	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG09	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG10	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A

Soil Gas			3rd Q	uarter 2000		4th Quarter 2000						
Monitoring Locations	H2 (ppm) Peak	H2 (ppm) Steady State	PH3 (ppm) Peak	PH3 (ppm) Steady State	HCN (ppm) Peak	HCN (ppm) Steady State	H2 (ppm) Peak	H2 (ppm) Steady State	PH3 (ppm) Peak	PH3 (ppm) Steady State	HCN (ppm) Peak	HCN (ppm) Steady State
0007SG01	0.00	0.00	0.00	0.00	N/A -	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG02	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG03	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG04	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG05	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG06	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG07	0.00	0.00	0.091	0.090	23.60	23.60	0.00	0.00	0.049	0.048	12.90	12.80
0007SG08	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A
0007SG09	0.00	0.00	0.054	0.053	12.90	12.70	0.00	0.00	0.058	0.057	12.20	12.00
0007SG10	0.00	0.00	0.00	0.00	N/A	N/A	0.00	0.00	0.00	0.00	N/A	N/A

* - Initial reading, which rapidly declined to zero.

N/A = Not Applicable, because no Phosphine was detected; therefore, no HCN readings were taken.